















Asko - 85




0018K	24x	0001K	12x	0013K	1x
		8x40			
0014K	4x	0074K	4x	0019K	16x
0017U	2x	0004K	8x	0009K	4x
0051K	1x	0109K	1x	0004V	4x
				4x30	
0026K	4x	0001V	9x	0013V	1x
		4x16		5x50	
0054K	16x	0123K	2x	0066K	4x




0004K	8x	0054K	8x	0018K	8x	0013K	1x




10.)




13.)




11.)



14.)



12.)



15.)

